

IN THE DRAWINGS:

Enclosed are red-lined mark-up copies of Figures 3, 4, 5, and 10 to correct minor errors in drawings. Applicant asserts that no new matter is added.

Amendments to Drawings:

Regarding Figures 3 and 5, an electrical connection between transistor 324 and 524 and column rapid discharge 333, 533, respectively, were missing on Column 0. Annotated Figures 3 and 5 have been amended to show this connection and replace Figures 3 and 5 as originally filed.

In Figure 4 electrical connection reference numeral “435” was missing. Annotated Figure 4 has been amended to include this reference number and replaces Figure 4 as originally filed. See Specification, Pg. 13, lines 17-18.

In Figure 10, has an incorrect label. Annotated Figure 10 has been amended by replacing the word “Charge” with “Discharge” and replaces Figure 10 as originally filed. See Specification, Pg. 16. lines 18-19.